


		PMX 1	PMX 2
Mechanical speed per minute	STROKES	25÷150	25÷120
Motors	KW	0,97	0,97
Power Absorption	KW	1,94 (Hot-melt + 3,9)	1,94 (Hot-melt + 3,9)
Air Consumption	NI/1'	17	17
Air Pressure	bar	5÷6	5÷6
Gross Weight	Kg.	1400	1400
Net Weight	Kg.	1050	1050



Size range	A			B			C			
	min.	15	12	65	20	15	65	125	75	200
	max.	80	75	200	125	75	200			
				A + B = max. 140			A + B = max. 170			

The above technical data is not binding and may be subject to change without prior notice.